

A REAL WORLD EXAMPLE OF MONITORING PROCESS SAFETY METRICS IN A REFINERY OVER FIVE YEARS

Bapco Operational Excellence Team

08 Month 2017



BIO

- Dr Mark Hodgkinson-PhD (chemistry), BSc (Hon) Chemistry
- Dr Mark Hodgkinson holds is currently the OEMS Project Manager for Bapco. He holds a PhD and BSc in Chemistry and Chemometrics. He has over 25 years' experience in the Oil and Gas Field and also 15 years in Applied Microbiology fields such as water treatment.
- His professional interests include: Operational Excellence, Operational Intelligence, System Design , Change management, Business planning and Multivariate processes monitoring
- His leisure interests include Historical Board Gaming and Golf.
- OE Team+++++++






OUR BEGINNINGS 2010







EARLY GENERATION OF METRICS

- Bapco implemented an Operational Excellence Management System over the top of all our Management systems including Process Safety Management .
- Each Process has Leading and Lagging indicators







Operational Excellence Culture



METRIC ATTRIBUTES

- All metrics are stated in the peak process documents (Process Descriptions) . We had leading and lagging indicators before API 754.
- An example of one (1) of the five (5) Leading indicators for this process


What is measured?	Leading: % Safety Critical Compliance checks for Relief Valves tests, Emergency Shutdown Device (ESD) tests and Over speed Trip Devices Tests (OTT). (PSV/RV, ESD Loops, Turbine trip tests)
Why is it measured?	Predicts this OEMS process performance by assessment of compliance.
Who measures it?	PMD – Maintenance Planning Section.
How is it measured?	Count of the actual checks and inspections performed against those that were scheduled for the month. Any re-schedule due to units unavailability counts as a miss.
Reporting format?	Tabular report to EHS Committee and Area Review and Monthly Tabular report via Operational Excellence Maintenance Measure (OEMM) by PMD Planning Section / XHQ.






METRIC ATTRIBUTES

- We used home built Spreadsheets to present summary results and detailed plots. All of this was very manual and ugly!
- Details of exactly what metrics to follow.








2013 ENHANCEMENTS





EARLY GENERATION OF METRICS

- Bapco implemented an Operational Intelligence
 Platform (Siemen XHQ) with the KPI
 Solution in built
- We realized that we needed "health or Risk" metrics as well as Leading and Lagging indicators (Hopkins 2007)





METRIC ATTRIBUTES

• The Lagging Indicator for the previous Leading Indicator.

What is measured?	Lagging; All Loss of Containment (API 754 T1, T2). This
	KPI measures the number of days between LOC events
Why is it measured?	Measures the performance of this process.
Who measures it?	QA Specialist
How is it measured?	All Loss of Containments in the incident Investigation Database
Reporting format?	Tabular report to EHS Committee and Area Review. / <i>XHQ</i>





THE CONCEPT (HOPKINS 2007)

- Leading Indicator
- Prediction from compliance, conformance, activities

• Health Indicator

Health

Lead

• The results of the Leading indicator activities

- Lagging Indicator
- Process Failure





What is measured?	Relief and Safety Valves found to be failed to danger (PSVs that failed their pop test) API 754 T3)
Why is it measured?	Gives an indication of the risk level this process must control.
Who measures it?	PMD/MSD but reported by Reliability Engineering Dept.
How is it measured?	Number of Safety Device checks that find that the device may not have worked as required.
Reporting format?	Tabular report to EHS Committee, Area Review and XHQ.



EARLY GENERATION OF METRICS

- KPI Functionality included
- A wrap up to an index
- RAG
- Bar Charts







2017 ENHANCEMENTS





Input Screen

VIZION OE/PSM

• State of the art, (best in class) KPI/KOP System.

Vizion OE				🚨 He	ello, BAPCODOM\xhqadmin!
Performance Indicators					
+ Add					
Name	: Туре	Category	i Impact	:	Order :
Tier 1 Process Safety Events	EHSC PSM	General	1	V T	1
Tier 2 Process Safety Events	EHSC PSM	General	2	V T	3
% Relief Valves Failures	EHSC PSM	General	3	VT	18
ESD Checks that Failed %	EHSC PSM	General	3	V T	19
Add missing values her LOCs	EHSC PSM	General	3	VT	5
Tier 3 SOL excursions	EHSC PSM	General	3	νт	5
All Inspections deferred YTD	EHSC PSM	General	4	VT	23
Clamps & Boxes on Hydrocarbon Lines	EHSC PSM	General	4	VT	21
Days exceeding alarm limits in month	EHSC PSM	General	4	VT	26
High risks (RR=16) at month end	EHSC PSM	General	4	VT	12
LOTO Checks conducted	EHSC PSM	General	4	V T	15
LOTO Score %	EHSC PSM	General	4	V T	16
Open Actions in Proces Safety or Fire	EHSC PSM	General	4	V T	20
Overdue MOCs	EHSC PSM	General	4	V T	7
Overdue Temporary MOCs	EHSC PSM	General	4	VT	8
PHA Actions Open	EHSC PSM	General	4	VT	11
PHAs to schedule YTD	EHSC PSM	General	4	V T	10



VIZION OE/PSM

• State of the art, (best in class) KPI/KOP System.


	ators Explorer	Status	:	Name	:	Projection	Impact 1
	All	-		Tier 1 Process Safety Events		1.714	1
	1			Tier 2 Process Safety Events			2
	EHSC CHES			Tier 3 SOL excursions		6.857	3
	4 EHSC Emergency	•		Tier 3 all other LOCs		29.14	3
				ESD Checks that Failed %		0	3
	11 EHSC Environment	-		% Relief Valves Failures	~~~~	0.8143	3
	3			PHAs to schedule YTD		10.29	4
	EHSC Health	-		Safety critical checks %		100	4
	2			LOTO Checks conducted	- T	60.33	4
	EHSC Hygiene	•		High risks (RR=16) at month end		0	4
	2			Overdue Temporary MOCs		0.5	4
	EHSC Leadership			PSSR Actions Open > 180 days		0	4
	14	-		Tier 4 Process Safety excursions		0	4
_	EHSC Personal Safety	-		Clamps & Boxes on Hydrocarbon Lines		54.67	4
	26 EHSC PSM			Days exceeding alarm limits in month		3.017	4
		-		Tier 1 LOC free days	7	82	4
	6 EHSC Road Safety	-		LOTO Score %	٦	96.7	4
				PTW Checks conducted	~~	231.2	4
		-		Unexpected Corrosion Events YTD		22	4
				All Inspections deferred YTD			4

Explorer



VIZION OE/PSM

• State of the art, (best in class) KPI/KOP System.





Bapco PSN METRICS MAP





אילפ PSM METRICS

990	PSM Process	Leading	Health/Risk	Lagging
	Process Safety Information.	Drawings and data sheet up date conformance		Incidents where a root cause includes PSI found to be missing or wrong.
	Process Hazard Analysis.	PHA to Schedule Open PHA Actions Overdue PHA actions	PHA Actions > Risk Rank X	Incident investigations that show the root cause includes PHA was not done or action item from PHA was not implemented in the specified time period.
	Operating Procedures	Ops and Mtce Document Reviews Over due	Ops and Mtce Documents changed per year	Incident investigations that show the root cause includes poor or missing document



....

PSM METRICS

PSM Process	Leading	Health/Risk	Lagging
Training	Mandatory Training conformance.		Incidents where a root cause includes Training Issues
Contractors Safety Management	% Contractor Safety Meetings to schedule	Number of safety violations by contractor	Contractors Statistics (LTI, NLTI, FA).
Pre-Start Up Safety Review	PSSR Actions overdue (180 days)		Lagging: PSSR faults -Post Start up PSSR incidents captured under Tier 4 : PSM incidents
Mechanical/Asset Integrity	Compliance of Statutory Checks /Inspections on equipment and safety critical devices LOTO, PTW checks	The result of the checks. Safe Operating Limit Excursions. Boxes/Clamps on H/C lines. Unexpected Corrosion events. Alarms levels.	Loss of Containments T1,T2, T3



6	PSM Process	Leading	Health/Risk	Lagging
	Safe Work Practice PTW, Isolation, Confined Space, Stop Work, Excavation. Others	Leading: Conformance to standard for working at heights, Excavation and Falling objects. BBS.	% Behavioural showing PPE Compliance PTW, LOTO, Safety Audit/checks/Inspecti on findings.	Lagging : Injury Frequency Rate
	Management of Change.	MOC's overdue Temporary MOC's O/D	MOC Audit findings	Incidents where MOC failure was a Root Cause.
	Incident Investigation	Overdue Incidents Investigations Near Miss to Incident ratio.	Incident Investigation CAPA close out rate	Repeat Incidents
	Emergency Planning and Response	Emergency Exercises Fire Drills	Fire Equipment Readiness	Fires API 754 T1, T2
	Compliance Audit Governance and Audit	Audits to schedule	Audit findings CAPA close out rate	Tier 1 and 2 HSE Incidents.



A WORKED EXAMPLE

iewer - Internet I	Explorer														
				4	☆ ⇒	10/09/17 13:34:	:52	5	3 0 4F	4.	<u>Эннр</u>	2			
Bapco	Marketing CD	NI Shinni	ng Boople	VizionOE											
Overview			My Views	VIZIONOL			Frends		▼ Ex	plorers		-			
view				Special F	ocus OD S	Safety Work Or	ders <mark>3</mark> Sa	afety Work Reque	ests Held 3		IMS Audits		Your Login ID 953959		
icu.			ROAYA Pro	ject: Clici	k this butt	on to avail a	chance to	win a prize –>	Quiz # 2	2			PEI Entry For	m	
erationa	I Audits	8			Special F	ocus OD Sa	fety Work O	rders <mark>3</mark> Sa	fety Work R	equests				Your Login ID	9
Audits Analyti	ics		Cli	ick any <mark>blu</mark>	e counts to	o filter the lists	and charts b	by that type						Rep	ort
PM	YTD				Туре				· · · · ·	artmer			dited Section		
	04/04/47	and	40/00/47	-	%			-	%		•	%		•	
Between	01/01/17		10/03/17	×	Auditor								cation		
					%				•	%	• •	%		•	
etrics		Checi	ks are Audits	performed	within the S	Section of the	Auditor		Issues	and the	eir Recurrences				
	Moc						Operational		Survey		Q. Question			Times Faile	d?
s Performed	14				1		45		LOTO		1 Have all energy s	ources been	identified?	6	
									LOTO		2 Has the energy s	ource been lo	ocked-out and or Tagged?	7	
	3 98	79 95	97	93	98	97	<u> </u>	87	LOTO		3 Has the owner st issued permit?	tipulated the L	ock-Out / Tag-Out on the	11	
000107 100									LOTO		4 Has the owner lo	cked-out the	source of energy?	7	
Metrics		Inspectio	ons are Audits	s performed	d outside th	ne Section of ti	he Auditor		LOTO			locked-out th	e source energy?		
s Performed	2	32	49	2	267	13		25						•	
													-		
ssues Noted	2	14	36	1	190	4		17							
Score / 100	91	97	95	97	96	98		86						-	
ouoc (4 voor r	olling)								LOTO		2	-		9	
sues (Tyear I	oming)								LOTO		-			3	
pections and	Checks				ssues				LOTO				in the Work Station / Contro	J 16	
				209	_				LOIO		Room?		In the work Station / Control	,	
				156					LOTO		14 Have all the tags	been entered	in the Clearance Card?	19	
				104					LOTO						
				52					LOTO 20	15				20	
10 11 12	01 02 03	04 05	06 07 08		10 11	12 01 02	03 04 05		LOTO 20	15	2 Has a mandatory	equipment is	olation/ blinding sketch beer	79	
16 16 16	17 17 17	17 17	17 17 17	16	16 16	16 17 17	17 17 17	17 17 17							
s & Checks - (Count: 2878														
Type Au	iditor			Auc	litorSecti	Audited Depa	artment	Audited Secti	on	Loca	tion	Issues	Comments		
	ben Anthony Ri	ivera (9534	50)	LSD	P_Complex	Oil Processing	- South	LSDP_Complex		#1HC	U	0	Change is commissioned		
READINE															
SS Jas	im Mohamed Jr	asim Mobid	Bu-Hussin (70)	1750) 0	th Decasa	Oil Drocessie	South	Couth Deser		NO.1		0	No commont-		
2014 Jas	an wonaned a	asimilation a	ba-nasain (700	500 500	un_Process	OII Processing	- 3000	South_Process	,	NU.4/	A CRODE (VACUUM)	U	No comments.		
PTW Jas	sim Mohamed Ja	asim Moh'd	Bu-Husain (700	0750) Sou	th_Process	Oil Processing	- South	South_Process	5	NO.4/	A CRUDE	0	No comments.		
2014			Du Unacia (70)	2750)	_			-							
PTW Jas 2014	sim Monamed Ja	asim Moh'd	Bu-Husain (700	Sou	th_Process	Oil Processing	- South	South_Process	3	NO.4/	A CRUDE (VACUUM)	0	No comments.		
	Bapco Remning Overview iew erationa Audits Analyti PM Between crics a Performed ssues Noted Score / 100 critics a Performed ssues Noted Score / 100 critics a Performed ssues Noted Score / 100 critics critics a Performed ssues Noted Score / 100 critics cr	Bapco Refining Marketing CC Overview Coverview iew erational Audits erational Audits Model Audits Analytics MOC PM YID Between 01/01/17 Score / 100 98 Metrics MOC Refrormed 14 ssues Noted 3 Score / 100 98 Metrics 2 Score / 100 91 sues (1 year rolling) 9 pections and Checks 0 10 11 12 0.1 0.2 0.3 10 11 12 0.1 0.2 0.3 10 11 12 0.1 0.2 0.3 10 11 12 0.1 0.2 0.3 10 11 12 0.1 0.2 0.3 10 11 12 0.1 0.2 0.3 10 11 12 0.1 0.2 0.3 10	Bapcole RefiningMarketing GDN Shipping Overview Image: Construction of the second of th	Bapcole Refining/Marketing GDN Shipping People Overview My Views ROAYA Pre- erational Audits Audits Analytics Clip Audits Analytics Clip PM YTD Between 01/01/17 and 10/09/17 Between 01/01/17 and 10/09/17 Atrics Checks are Audits Ad44 ssues Noted 3 79 196 Score / 100 98 95 97 Metrics Inspections are Audits Ad44 asues Noted 2 14 36 Score / 100 91 97 95 stues (1 year rolling) pections and Checks Auditor operatin Ruben Anthony Rivera (953450) ORATI Ruben Anthony Rivera (953450) ONAL ReADINE SS S SS Y Jasim Mohamed Jasim Moh'd Bu-Husain (701/2014	Expecting Constraints of the second sec	Bapco Refining/Marketing GDN Shipping People VizionOE Overview My Views Special Focus 0.04 Relational Audits Special Focus 0.04 Relational Audits Click any blue counts to Special Focus Special Focus 0.04 Relational Audits Click any blue counts to Special Focus Type Number of Special Focus 0.04 Multis Analytics Click any blue counts to Special Focus Type Number of Special Focus 0.04 PM YID Special Focus Views Special Focus 0.04 Between 01/01/17 and 10/09/17 Special Focus 0.04 Special Focus Checks are Audits performed within the Special Focus Number of Special Focus Number of Special Focus 0.10 Special Focus MOC Safety LOTO 2015 LOTO DIO PTW 201 Special Focus MOC Safety LOTO 2015 LOTO DIO PTW 201 Special Focus MoC Safety LOTO 2015 LOTO DIO DIO DIO DIO DIO DIO Saf	Interventional Auditors Interventional Auditors Interventional Audits Interventional Interventin Interventional Interventiona	Holey 11 234-52 Hy Trends Coverview My Trends Second Focus Obstrey Work Order My Trends Production Modeling My Trends Second Focus Obstrey Work Order Second Second Focus Obstrey Work Order Second Second Focus Obstrey Work Order Second Second	Boron Reference Handland CDRS Shippands Resource Overview My Views Viewn View View My Trends Ny Trends ROATA Project: Click this button to avail a chance to win a price erational Audits My Views OS Safety Work Orders 3 Safety Work Order 3 Safety Work Orders 3 Safety W	Interview Interview	Image: State of the state	Integring and a set of the s	In the section of the Audior In the sectin the Audior In the section and the section	the market of the field of the second o	Image: Control of the state state and charts by the state s






A WORKED EXAMPLE

Audit Information

						-sues and t	their R	Recurrences		
Date / 1	Time	Survey De	partment	Survey Location		urvey	Q.	Question A		Times Failed?
Receiving Authority: Description of Work: Safe Work Permit Number Associated Certificates/ Form Auditor Auditor Ahmed Hasan Ahmed Asho Badge 708795 Question 1 Is the scope of work of	17 11:41:00 PM	Oil Proces	ssing - North	NO.1 VDU						rintee r anea.
8/22/2017 11:41:00 PM Survey Type PTW 2014 Additional Information Receiving Authority: Description of Work: Safe Work Permit Number Associated Certificates/ Forms Auditor Auditor Auditor Ahmed Hasan Ahmed Ashoo Badge 708795 Question 1 Is the scope of work design of the store	Ту ре	Survey Se	ction	Org Code		W 2014	14	RAMS?	or the task, clearly specified on	
Survey Type PTW 2014 Additional Information Receiving Authority: Description of Work: Safe Work Permit Number Associated Certificates/ Forms Auditor Auditor Ahmed Hasan Ahmed Ashoo Badge 708795 Question Is the scope of work de 2 Are necessary risk asses		North_Pro	cess	03RN11		100 2014	14	the isolation certificate, and		
Additio	nal Information					W 2014	2	Are necessary risk assess	ments available for review?	
Receivin	g Authority:		874215			W 2014	7	Are other area or system at	ctivities cross-referenced	
Descript	ion of Work:		inspect burner of hea	ter 2F1		W 2014	22	correctly via the permit?	checks being carried out and	1
Safe W o						11 2014		recorded on the original cop	-	-
Associa	sociated Certificates/ Forms JSA:ICC:		JSA:ICC:			TW 2014	9	Are signatures and initials tr	raceable and legible?	2
Audito	\uditor					W 2014	16	Are the right people aware	of isolated equipment?	2
		Departmer	nt	Org Code			20	Are tools and equipment sui	itable and in good condition?	16
Ahmed	l Hasan Ahmed Ashoor	Oil Proces	ssing - North	03RN11		W 2014	13	Do people know what to do	in the event of emergency?	
Badge	3adge		Section							
708795	_		ocess		TW 2014	23	Have the SWP and associat cancelled properly?	ated Certificate forms been	3	
					Answer	TW 2014	17	Is the Owner Dept. aware o	of the work?	17
1					YES					_
2	2 Are necessary risk assessments available for review ?				YES	W 2014	5	Is the operational time limit o extensions properly authori		8
3	Are identified hazards liste	d on the pe	rmit to work, JSA or RA	MS?	YES	W 2014	1	is the scope of work clearly		4
4	Are appropriate precaution specified isolations)?	ns listed on t	the permit to work (inc	luding clearly YES		TW 2014	18	Is the work being carried ou		4
5	Is the operational time lim authorised?)	it of the per	mit clear? (are extensio	YES			permit and associated certif	ficates?		
6	Are certificates completed	properly an	d appended to the per	mit?	YES					
7	Are other area or system	activities cro	ss-referenced correctly	via the permit?	N/A					
8	Are copies of permits, cer	tificates and	attachments legible?		YES					
9	Are signatures and initials	traceable an	d legible?		YES					
10	Are copies of permits and	certificates	posted at the correct lo	cations?	YES					
11	Are attachments, drawing	s etc. held a	at the correct locations	?	N/A					
12	Are Users briefed on the p understanding of requirem		ork, and have they ackn	ow ledged	YES					
13	13 Do people know what to do in the event of emergency?			YES						
14 Are isolations appropriate for the task, clearly specified on the isolation certification and correctly implemented?			isolation certificate,	YES						
15	15 Are common isolations cross-referenced?		N/A							
16	Are the right people awar	e ofisolated	equipment?		YES					
17	Is the Owner Dept. aware	of the wor	k?		YES					
18	Is the work being carried certificates?	out in confo	rmance with the permit	t and associated	YES					
			the state of the second second	ropriate for the task?	VEC					



بابکو Bapco

THANK YOU